

HW-4 红外线非接触式温度计

1. 红外线非接触式/手持式/笔式
2. 测量范围35.5°C-42.9°C
3. 测量范围0°C-118°C
4. 测量精度±0.2°C
5. 测量精度±0.3°C
6. 测量精度±1°C
7. 测量精度±0.1°C
8. 测量精度±10.0°C
9. 测量精度±40.0°C
10. 测量精度±80.0°C

符合EN 12470-5和ASTM 1965-98
测量范围1CM-2CM
测量精度
±0.2°C 35.5-42.0°C ±0.3°C 42.1-42.9°C
±1°C 0-118°C
±0.1°C
±10.0°C 40.0°C
±80.0°C
-25.0°C~55.0°C
90°
2 * 4 * 41mm * 40mm * 152mm
108g




红外线非接触式

□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□
 □□/ ctn□60pcs / ctn
 G.W./ctn□12KG
 Ctn□□□□56 * 39 * 33CM
 □□□
 MOQ□1000PCS
 □□□□□□25□30□
 CE0499□□□□RoHS□□
 □□□□□□20,000pcs□



Error less than or equal to $\pm 0.2^{\circ}\text{C}$

Is accurate measure



□□□□□□sanieleung@dor-medex.com
 □□□□□□thermometersupplier.com