

Medexpro provides top quality masks which can be printed [logo](#).If you are interested ,pls enquiry me .

Our [masks](#) are all 3D design and there are six kinds.




Professional manufacturer of [mask](#) with enough in stock.

Customers items

The custom product itself belongs to the particularity.After confirming the customized sample,the product cannot be changed.It is suggested to confirm the information with the customer service

before production.



Steps for usage

step 1

Open the [mask](#), nose clip out. Both hands were pulled side of the band, so that the nose folder above the mask.

step 2

Put the mask against the chin.

step 3

Pull the band to the ear.

step 4

Place your hands in the middle of the metal nose clip. From the middle of the nose by the status quo, until close to the bridge of the nose.

step 5

Into the work area. Feel the air leak from the nose, should be re-adjust the nose clip. If you feel no air overflow can enter the work area.

